

02 July 2009

NON-INCIDENT / NON-ACCIDENT STATEMENT

We have reviewed the maintenance records / documents on file of the LPT Shaft from Engine CFM56-3B S/N 724-675 and found that the unit have not been involved in any incident / accident or subjected to extreme heat, fire or stress.

DESCRIPTION	P/N	S/N	TSN / CSN
LPT Shaft	301-330-067-0	F001908	21824:47 H / 25938 C


ARNULFO T. AGAN

Vice President

Aircraft Engineering Department

Philippine Airlines