

15 February 2010

NON-INCIDENT / NON-ACCIDENT STATEMENT

We have reviewed the maintenance records / documents on file of the LPT Shaft from Engine CFM56-3 S/N 724-733 and found that the unit have not been involved in any incident / accident or subjected to extreme heat, fire or stress.

DESCRIPTION	P/N	S/N	TSN / CSN
LPT Shaft	301-330-067-0	F002148	27110 H / 26706 C


ARNULFO T. AGAN
Vice President
Aircraft Engineering Department
Philippine Airlines