

02 July 2009

## NON-INCIDENT / NON-ACCIDENT STATEMENT

We have reviewed the maintenance records / documents on file of the Booster Spool from Engine CFM56-3B S/N 724-417 and found that the unit have not been involved in any incident / accident or subjected to extreme heat, fire or stress.

DESCRIPTION	P/N	S/N	TSN / CSN
Booster Spool	335-009-306-0	J116550	21426:59 H / 24971 C

  
**ARNULFO T. AGAN**

Vice President  
Aircraft Engineering Department  
Philippine Airlines