


24 June 2009

NON-INCIDENT / NON-ACCIDENT STATEMENT

We have reviewed the maintenance records / documents on file of the Fan Shaft from Engine CFM56-3B S/N 724-392 and found that the unit have not been involved in any incident / accident or subjected to extreme heat, fire or stress.

DESCRIPTION	P/N	S/N	TSN / CSN
Fan Shaft	335-006-414-0	R000335	25890:35 H / 24731 C


ARNULFO T. AGAN
Vice President
Aircraft Engineering Department
Philippine Airlines